



## Service Prices

### أسعار الصيانة

Car Model		15,000	30,000	45,000	60,000	75,000	90,000	105,000	120,000
Jetta 2.0	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1440	690	1050	690	1440
	Total Part				1862.3	726.2	961.4	726.2	1862.3
	<b>Grand Total</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>3302.3</b>	<b>1416.2</b>	<b>2011.4</b>	<b>1416.2</b>	<b>3302.3</b>
CC 4cyl	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1440	690	1050	690	1440
	Total Part				1388.85	759.9	1174.7	759.9	1388.85
	<b>Grand Total</b>	<b>690</b>	<b>1,050</b>	<b>690</b>	<b>2,829</b>	<b>1,450</b>	<b>2,225</b>	<b>1,450</b>	<b>2,829</b>
Jetta 2.5	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1,440	690	1,050	690	1,440
	Total Part				1,855	876	1,141	876	1,855
	<b>Grand Total</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>3294.95</b>	<b>1566.4</b>	<b>2191</b>	<b>1566.35</b>	<b>3294.95</b>
Teramont 2.0	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1440	690	1050	690	1440
	Total Part				2696.9	790.1	1195.4	790.1	2696.9
	<b>Grand Total</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>4,137</b>	<b>1,480</b>	<b>2,245</b>	<b>1,480</b>	<b>4,137</b>
CC V6	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1,440	690	1,050	690	1,440
	Total Part				2,409	647	800	647	2,409

	<b>Grand Total</b>	<b>690</b>	<b>1,050</b>	<b>690</b>	<b>3,849</b>	<b>1,337</b>	<b>1,850</b>	<b>1,337</b>	<b>3,849</b>
<b>Tiguan (DSG)</b>	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1440	690	1050	690	1440
	Total Part				2250.8	824.9	1319.5	824.9	2250.8
	<b>Grand Total</b>	<b>0</b>	<b>1,050</b>	<b>0</b>	<b>3,691</b>	<b>1,515</b>	<b>2,369</b>	<b>1,515</b>	<b>3,691</b>
<b>Tiguan 2.0</b>	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1,440	690	1,050	690	1,440
	Total Part				2,132	825	1,240	825	2,132
	<b>Grand Total</b>	<b>0</b>	<b>1,050</b>	<b>0</b>	<b>3,572</b>	<b>1,515</b>	<b>2,290</b>	<b>1,515</b>	<b>3,572</b>
<b>Touareg</b>	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1,440	690	1,050	690	1,440
	Total Part				3,152	985	1,650	985	3,152
	<b>Grand Total</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>4,592</b>	<b>1,675</b>	<b>2,700</b>	<b>1,675</b>	<b>4,592</b>
<b>Arteon</b>	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1,440	690	1,050	690	1,440
	Total Part				2,209	712	1,122	712	2,209
	<b>Grand Total</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>3,649</b>	<b>1,402</b>	<b>2,172</b>	<b>1,402</b>	<b>3,649</b>
<b>Touareg 2003-2012</b>	T.U.	1	2	1.5	4	1.5	2	1.5	4
	Total Labor				1,200	450	600	450	1,200
	Total Part				2,310	644	819	644	2,310
	<b>Grand Total</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>3,510</b>	<b>1,094</b>	<b>1,419</b>	<b>1,094</b>	<b>3,510</b>
<b>Teramont 3.6</b>	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1,440	690	1,050	690	1,440
	Total Part				3,088	957	1,586	957	3,088
	<b>Grand Total</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>4,528</b>	<b>1,647</b>	<b>2,636</b>	<b>1,647</b>	<b>4,528</b>
<b>Beetle</b>	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1440	690	1050	690	1440

	Total Part				2,284	868	1,273	868	2,284
	<b>Grand Total</b>	<b>690</b>	<b>1,050</b>	<b>690</b>	<b>3,724</b>	<b>1,558</b>	<b>2,323</b>	<b>1,558</b>	<b>3,724</b>

<b>Golf GTI</b>	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1,440	690	1,050	450	1,440
	Total Part				2,459	1,045	1,447	1,045	2,459
	<b>Grand Total</b>	<b>690</b>	<b>1,050</b>	<b>690</b>	<b>3,899</b>	<b>1,735</b>	<b>2,497</b>	<b>1,495</b>	<b>3,899</b>
<b>Golf R</b>	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1,440	690	1,050	690	1,440
	Total Part				2,295	865	1,284	865	2,295
	<b>Grand Total</b>	<b>690</b>	<b>1,050</b>	<b>690</b>	<b>3,735</b>	<b>1,555</b>	<b>2,334</b>	<b>1,555</b>	<b>3,735</b>
<b>Passat 2.5</b>	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1,440	690	1,050	690	1,440
	Total Part				2,242	1,471	1,141	1,471	2,277
	<b>Grand Total</b>	<b>690</b>	<b>1,050</b>	<b>690</b>	<b>3,682</b>	<b>2,161</b>	<b>2,191</b>	<b>2,161</b>	<b>3,717</b>
<b>Golf 1.2</b>	T.U.				4.8	2.3	3.5	2.3	4.8
	Total Labor				1440	690	1050	450	1440
	Total Part				1,358	771	1,144	771	1,358
	<b>Grand Total</b>	<b>690</b>	<b>1,050</b>	<b>690</b>	<b>2,798</b>	<b>1,461</b>	<b>2,194</b>	<b>1,221</b>	<b>2,798</b>
<b>Golf GTI 2003 - 2013</b>	T.U.	1	2	1.5	4	1.5	2	1.5	4
	Total Labor				1,200	450	600	450	1,200
	Total Part				1,806	583	724	583	1,806
	<b>Grand Total</b>	<b>300</b>	<b>600</b>	<b>450</b>	<b>3,006</b>	<b>1,033</b>	<b>1,324</b>	<b>1,033</b>	<b>3,006</b>
<b>Scirocco R</b>	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1440	690	1050	690	1440
	Total Part				2029.35	748.35	793.5	748.35	2029.35
	<b>Grand Total</b>	<b>690</b>	<b>1,050</b>	<b>690</b>	<b>3,469</b>	<b>1,438</b>	<b>1,844</b>	<b>1,438</b>	<b>3,469</b>

<b>Scirocco 2.0</b>	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1,440	690	1,050	690	1,440
	Total Part				2,101	820	1,243	820	2,101
	<b>Grand Total</b>	<b>690</b>	<b>1,050</b>	<b>690</b>	<b>3,541</b>	<b>1,510</b>	<b>2,293</b>	<b>1,510</b>	<b>3,541</b>
<b>New Tiguan 1.4</b>	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1440	690	1050	690	1440
	Total Part				2,147	1,316	1,136	1,316	2,147
	<b>Grand Total</b>	<b>690</b>	<b>1,050</b>	<b>690</b>	<b>3,587</b>	<b>2,006</b>	<b>2,186</b>	<b>2,006</b>	<b>3,587</b>
<b>New Tiguan 2.0</b>	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1,440	690	1,050	690	1,440
	Total Part				2,304	865	1,267	865	2,304
	<b>Grand Total</b>	<b>690</b>	<b>1,050</b>	<b>690</b>	<b>3,744</b>	<b>1,555</b>	<b>2,317</b>	<b>1,555</b>	<b>3,744</b>
<b>New Touareg 2019</b>	T.U.	2.3	3.5	2.3	4.8	2.3	3.5	2.3	4.8
	Total Labor				1,440	690	1,050	690	1,440
	Total Part				3,833	1,071	1,980	1,071	3,833
	<b>Grand Total</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>5,273</b>	<b>1,761</b>	<b>3,030</b>	<b>1,761</b>	<b>5,273</b>